

**INDEX OF TREE-RING DATED BUILDINGS IN WALES**  
**COUNTY LIST approximately in chronological order, revised to VA51 (2020).**

© Vernacular Architecture Group 2021

These files may be copied for personal use, but should not be published or further distributed without written permission from the Vernacular Architecture Group. Always access these tables via the VAG website. Unauthorised copies released without prior consent on search engines may be out of date and unreliable. Enquiries may be made to bob@bmeeson.co.uk



Before using the index you are recommended to read or print the *introduction and guidance*, which includes a key to the abbreviations used on the tables.

**CARMARTHENSHIRE (Sir Gaerfyrddin)**

County-historic (later)	Felling date range	Placename	Address	VA ref; lab (other ref) <i>Cof</i>	Description / keywords	NGR
Carm (Dyfed)	1531 -61 i	Dyffryn Cennen	Cwrt Bryn-y-beirirdd	51.111	Hall and wing. Cusped collar trusses over wing. Date range is for inserted ceiling beam.	SN 663180
Carm (Dyfed)	1531 + to 1567 +	Llandeilo	Aberglasney House	30,112 Oxf	Ex-situ timbers from roof of rear service range yielded various dates; c.1600 suggested. (For hall ceiling see 1712 -42, and for main range roof see 1771).	SN 581221
Carm (Dyfed)	1726 +	Llandeilo	Newton House, Dinefwr Park	31.118 UoW (NT / Cadw)	Floorboards imported from Germany?	SN 614225
Carm (Dyfed)	1712 -42	Llandeilo	Aberglasney House	30,112 Oxf	Hall ceiling: double tenoned joist. (For ex-situ timbers from service range roof see c.1600 & for main range roof see 1771).	SN 581221
Carm (Dyfed)	1769 /70 i	Baneyffordd	Llwynffynnon Uchaf	51.111	2-storey farmhouse with central hall and stair plan. Dates are from lintel and 2 posts.	SN 405386
Carm (Dyfed)	1770 & 1771	Llandeilo	Aberglasney House	30,112 Oxf (1)	Reconstruction of front range roof with king post trusses. (For ex-situ timbers from service range roof see c.1600 & for hall ceiling see 1712 -42).	SN 581221
Carm (Dyfed)	1793 /94 & 1796	Llansadwrn, nr. Llandeilo	Aberdeunant	29.127 Oxf	Soffit-pegged jointed cruck in a 2-unit 2-storey central entry end chimney cottage. (Now an outbuilding).	SN 671307

**REFERENCES**

<sup>1</sup> *Post-med. Archaeol.*, 55 (1999), 270 -76.